

APPENDIX H

**Recommendations
from Research and
Consultation**

Appendix H

ID	MAIN ROAD	SIDE	CROSS ROAD	ISSUE	SOURCE	ACTION	UNIT	PRIORITY	COST*
A020	Botany Rd		Raglan St	Accident cluster - 6	Accident Analysis	consider doing a road safety audit		L	\$8,000
A021	Cleveland St		Wilton St	Accident cluster - 7	Accident Analysis and T&UP study	Action September 2000 audit recommendations (see below)	20	L	\$3,500
A021	Cleveland St		Wilton St			pedestrian fence along median east of intersection		L	\$5,000
A021	Cleveland St		Wilton St			consider additional lighting		L	\$3,000
A021	Cleveland St		Wilton St			kerb blister on Walker St		L	\$7,000
A022	Cleveland St		Crown St/Baptist St	Accident cluster - 16	Accident Analysis and T&UP study	pedestrian fence along median east and west of intersection	40	L	\$5,000
A022	Cleveland St		Crown St/Baptist St			consider additional lighting		L	\$8,000
A023	Cleveland St		Bourke St	Accident cluster - 7	Accident Analysis	consider doing a road safety audit		L	\$8,000
A024	Cleveland St		Elizabeth St	Accident cluster - 9	Accident Analysis	consider doing a road safety audit		C	\$8,000
A025	Elizabeth St		Phillip St	Accident cluster - 8	Accident Analysis	consider doing a road safety audit		C	\$8,000
A026	Elizabeth St		Phillip St	Accident cluster - 8	Accident Analysis	consider doing a road safety audit		C	\$8,000
A027	Flinder St		South of Oxford St	Accident cluster - 17	Accident Analysis	consider doing a road safety audit		C	\$8,000
A028	Gibbons St		South Dowling St	Accident cluster - 5	Accident Analysis	consider doing a road safety audit		C	\$8,000
A029	Gibbons St		Lawson St	Accident cluster - 8	Accident Analysis	consider doing a road safety audit		C	\$8,000
A030	Oxford St		Palmer St	Accident cluster - 5	Accident Analysis	Review proposed Oxford Street upgrades, road safety audit		H	\$8,000
A031	Oxford St		Taylor Sq	Accident cluster - 35	Accident Analysis	Review proposed Oxford Street upgrades, road safety audit		H	\$8,000
A032	Oxford St		South Dowling St	Accident cluster - 6	Accident Analysis	Review proposed Oxford Street upgrades, road safety audit		H	\$8,000
A033	Oxford St		Oatley St	Accident cluster - 5	Accident Analysis & Submission	Action July 2002 audit recommendations (see below)		L	\$2,000
A033	Oxford St		Oatley St			relocation of western crossing to improve visibility		L	\$5,000
A033	Oxford St		Oatley St			consider additional lighting		L	
A033	Oxford St		Oatley St			consider turning arrow hold on Oatley Road		L	
A033	Oxford St		Oatley St			consider exclusive pedestrian phase		L	
A034	Oxford St		west of Taylor Sq	Accident cluster - 9	Accident Analysis	Review proposed Oxford Street upgrades, road safety audit	1	H	\$8,000
A035	Oxford St		Crown St	Accident cluster - 32	Accident Analysis	Review proposed Oxford Street upgrades, road safety audit		H	\$8,000
A036	Redfern St		Pitt St	Accident cluster - 5	Accident Analysis	consider doing a road safety audit		L	\$8,000
A037	Regent St		Redfern St	Accident cluster - 13	Accident Analysis	consider doing a road safety audit		L	\$8,000
A038	Elizabeth St		Redfern St to Kettle St	elderly pedestrian, mid block	Accident Analysis	consider doing a road safety audit		L	\$8,000
A050	Belvoir St	north	Clisdel St to Ward Park	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	1	L	\$1,900
A051	Chalmers St	east	Phillip St to Redfern St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	2	L	\$3,800
A052	Devonshire St	south	Chalmers St to Crown St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	5	L	\$9,500
A053	Devonshire St	south	Chalmers St to Crown St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	5	L	\$9,500
A054	Kettle St	south	Redfern Park to Morehead St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	1	L	\$1,900
A056	Kettle St	north	Redfern Park to Morehead St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	1	L	\$1,900
A057	Morehead St	east	Redfern St to Phillip St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	2	L	\$3,800
A058	Morehead St	west	Redfern St to Phillip St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	2	L	\$3,800
A059	Phillip St	north	Young St to Morehead St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	1	L	\$1,900
A060	Phillip St	south	Cope St to Chalmers St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	3	L	\$5,700
A061	Pitt St	west	Raglan St to Phillip St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	1	L	\$1,900
A062	Raglan St	south	Botony Rd to Pitt St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	3	L	\$5,700
A063	Raglan St	south	Botony Rd to Pitt St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	3	L	\$5,700
A064	Redfern St	south	Chalmers St to Young St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	3	L	\$5,700
A085	Young St	west	Redfern St to Phillip St	Ambulatory disabilities eg elderly	Study recommendation	install AS seating @ 100m	2	L	\$3,800
A066	Devonshire St		see report Section 5.6.1	directional signage	Study recommendation	provide directional signage at Station entrance and along route	7	H	\$2,520
A067	Devonshire St		see report Section 5.6.1	steep gradient	Study recommendation	consider hand rail along steep sections	150	H	\$9,000
A001	Crown St		Landsdowne	lack of pedestrian crossing	Submission	investigate crossing warrant, consider blisters		L	\$3,000
A004	Oxford St		Riley St	lack of crossing on western arm	submission	Review proposed Oxford St upgrades, consider new crossing and signal phasing change (not part of South Sydney)		L	
A005	Riley St		Reservoir St	lack of pedestrian crossing	Submission	new crossing approved		C	
A011	Campbell St		Hunt St	Dangerous crossing	Submission	improve signage and lighting		L	\$5,360
A012	Moore Park Rd		Oatley Rd	lack of pedestrian crossing	Submission	consider new signals		L	\$100,000
A014	South Dowling Street		Anzac parade to Oxford Street	Lack of pedestrian crossing	Submission	consider new crossing		L	\$100,000
A015	Oxford St		Barcom St, South Dowling	no crossing on east arm	Submission	consider new crossing		L	\$20,000
A003	Moore Park Rd		Anzac Parade	lack of crossing on eastern arm	submission, audit	consider new crossing.		L	\$100,000
A003						in interim, install pedestrian sign to direct to Greens Rd Crossing		L	\$360
A013	Raglan St		George St	dangerous crossing	submission, audit	improve lighting, advance warning signs and road markings		L	\$6,660

