

MAIN STREET HERITAGE PAINT SCHEME

FOR

KING STREET, NEWTOWN
ENMORE ROAD, ENMORE

BUILDING DATA SHEETS
PART 5 - No.538-672 King Street



Historic Photo

Address 538-540 KING ST
LGA ☒ South Sydney ☐ Marrickville

Owner MR & MRS. N. ZERVOS
Address 48 JUDD ST, BANKSIA, 2216.

Present name INNER CITY FLEET MAINTENANCE
Present use CAR REPAIR.

Former name
Former use

Date/period
Architectural style

Streetscape contribution

☐ Significant ☒ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date
Source

Information source/s

Recommended conservation action

• REDESIGN SIGNAGE - REFER SIGN CODE.

Suggested colour scheme(s)

EXISTING ACCEPTABLE



Historic Photo

Address 542-544 KING ST
LGA ☒ South Sydney ☐ Marrickville

Owner THE NEW THEATRE LTD.
Address

Present name NEW THEATRE
Present use THEATRE.

Former name
Former use

Date/period 1920's, REMODELLED IN 1980's.
Architectural style

Streetscape contribution

- ☐ Significant ☐ Contributory
☐ Borderline ☒ Non-contributory

Heritage listings

- ☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date
Source

Information source/s

Recommended conservation action

Suggested colour scheme(s)

NC RANGE



Historic Photo

Address 546

LGA ☒ South Sydney ☐ Marrickville

Owner SYDNEY CENTRAL REGION AUSTRALIA POST.

Address G.P.O. BOX 8000, SYDNEY, 2001.

Present name NEWTOWN SOUTH POST OFFICE.

Present use POST OFFICE.

Former name

Former use

Date/period

Architectural style

Streetscape contribution

☐ Significant

☐ Contributory

☐ Borderline

☒ Non-contributory

Heritage listings

☐ Heritage Act

☐ Council LEP

☐ National Trust

☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

Suggested colour scheme(s)

N/A



Historic Photo

Address

LGA ☒ South Sydney ☐ Marrickville

Owner SYDNEY CENTRAL REGION AUSTRALIA POST
Address G.P.O. BOX 8000, SYDNEY, 2001.

Present name NEWTOWN SOUTH POST OFFICE
Present use POST OFFICE.

Former name
Former use

Date/period
Architectural style

Streetscape contribution

☐ Significant ☐ Contributory
☐ Borderline ☒ Non-contributory

Heritage listings

☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date
Source

Information source/s

Recommended conservation action

Suggested colour scheme(s)

N/A



Historic Photo

Address 564-566 KING ST
LGA ☒ South Sydney ☐ Marrickville

Owner STONEHEDGE PROPERTIES P/L.
Address % MAYNE NICKLESS LTD ARMAGUARD UNIT.
1ST FLOOR, 390 ST KILDA RD.

Present name ARMAGUARD.
Present use COMMERCIAL

Former name
Former use

Date/period c 1900.
Architectural style VICTORIAN FILIGREE

Streetscape contribution

☐ Significant ☒ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Recommended conservation action

• RESTORE BUILDING TO ORIGINAL DETAIL.

Photo date

Source

Information source/s

Suggested colour scheme(s)

AS ORIGINALLY.



Historic Photo

Address 568-570 KING ST
LGA ☒ South Sydney ☐ Marrickville

Owner STONEHEDGE PROPERTIES P/L
Address MAYNE NICKLESS LTD, ARMAGUARD UNIT
1 ST FLOOR, 340 ST KILDA RD.

Present name ARMAGUARD
Present use COMMERCIAL.

Former name
Former use

Date/period
Architectural style

Streetscape contribution

☐ Significant ☐ Contributory
☐ Borderline ☒ Non-contributory

Heritage listings

☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Recommended conservation action

Photo date

Source

Information source/s

Suggested colour scheme(s)

NC RANGE



Historic Photo

Address 572-574 KING ST.

LGA ☒ South Sydney ☐ Marrickville

Owner STONEHEDGE PROPERTIES P/L

Address MAYNE NICKLESS LTD, ARMAGUARD UNIT,
1ST FLOOR, 390 ST KILDA RD.

Present name ARMAGUARD

Present use COMMERCIAL.

Former name

Former use

Date/period

Architectural style FEDERATION FREE CLASSICAL.

Streetscape contribution

- ☐ Significant ☒ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

- ☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

- REMOVE SCREENS & RESTORE FIRST FLOOR WINDOW OPENINGS TO ORIGINAL APPEARANCE.

Suggested colour scheme(s)

FED: C OR D



Historic Photo

Address 576 - 582 KING ST.
LGA ☒ South Sydney ☐ Marrickville

Owner VERANU P/L
Address



Present name UNION HOTEL
Present use HOTEL.

Former name UNION HOTEL
Former use HOTEL.

Date/period
Architectural style INTER-WAR FUNCTIONALIST.

Streetscape contribution

☒ Significant ☐ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date

Source

AND ARCHIVES OF
BUSINESS OF LABOR (TOOTHYCO)

Information source/s

Recommended conservation action
• CLEAN BRICKWORK.

Suggested colour scheme(s)

AS ORIGINALLY



Historic Photo

Address 590 - 594 KING ST.
LGA ☒ South Sydney ☐ Marrickville

Owner MR. L. RADOM.
Address 50 MINNAMURRA RD, NORTHBRIDGE,
2063.

Present name AFRICAN ART
Present use RETAIL

Former name
Former use

Date/period c1898.
Architectural style

Streetscape contribution

☐ Significant ☒ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Recommended conservation action

- RETAIN ORIGINAL SHOPFRONT.
- REINSTATE CANTILEVERED AWNING.

Photo date

Source

Information source/s

Suggested colour scheme(s)

FBK: A or D



Historic Photo

Address 596 KING ST

LGA ☒ South Sydney ☐ Marrickville

Owner MAGDALA P/L % CRYSTAL R/E

Address 103 KING ST, NEWTOWN.

Present name

Present use RESIDENTIAL.

Former name

Former use

Date/period c 1900

Architectural style VICTORIAN FILIGREE.

Streetscape contribution

- ☐ Significant ☒ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

- ☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

- REPAIR SLATE ROOF.
- REINSTATE CAST IRON BALCONY TO FIRST FLOOR BALCONY.
- REPLACE WIRE FENCE WITH TRADITIONAL FENCE.

Suggested colour scheme(s)

VIC: A, B or E



Historic Photo

Address 598-602 KING ST.

LGA ☒ South Sydney ☐ Marrickville

Owner DR. H.W. FABER % NEWTOWN R/E

Address 190 KING ST, NEWTOWN, 2042.

Present name

Present use RESIDENTIAL.

Former name

Former use

Date/period c 1900

Architectural style VICTORIAN FLIGREE.

Streetscape contribution

- ☐ Significant ☒ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

- ☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

- RESTORE BUILDINGS TO ORIGINAL DETAIL.
- REINSTATE TRADITIONAL FENCES.

Suggested colour scheme(s)

VIC: A, B OR E



Historic Photo

Address 604 KING ST.

LGA ☒ South Sydney ☐ Marrickville

Owner MR & MRS. I.G. JUSUFOVIC.

Address 14 WEST BOTANY ST, ARNCLIFFE
2205.

Present name

Present use RETAIL.

Former name

Former use

Date/period

Architectural style

Streetscape contribution

- ☐ Significant ☒ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

- ☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

- RETAIN GROUND FLOOR SHOPFRONT.

Suggested colour scheme(s)

FBK: A or B



Historic Photo

Address 606-608 KING ST.
LGA ☒ South Sydney ☐ Marrickville

Owner EST LATE M & MRS. M. DROSSOS.
Address 608 KING ST, NEWTOWN, 2042.

Present name
Present use COMMERCIAL/RETAIL.

Former name
Former use

Date/period c 1900
Architectural style VICTORIAN FILIGREE.

Streetscape contribution

☐ Significant ☒ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date
Source

Information source/s

Recommended conservation action

• REINSTATE CAST IRON BALCONY TO
N° 608

Suggested colour scheme(s)

VIC: A OR B



Historic Photo

Address 610 KING ST.

LGA ☒ South Sydney ☐ Marrickville

Owner MRS. J.I. LUTSCHENKOW.

Address 610 KING ST, NEWTOWN, 2042.

Present name

Present use RESIDENTIAL.

Former name

Former use

Date/period

Architectural style

Streetscape contribution

☐ Significant

☐ Contributory

☒ Borderline

☐ Non-contributory

Heritage listings

☐ Heritage Act

☐ Council LEP

☐ National Trust

☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

• RETAIN EXISTING LEADLIGHTS.

Suggested colour scheme(s)

NC RANGE



Historic Photo

Address 612-622 KING ST.
LGA ☒ South Sydney ☐ Marrickville

Owner MR & MRS. W.G. ROBINSON
Address 14 CABRAMATTA ST, CRONULLA,
2230.

Present name
Present use RETAIL.

Former name
Former use

Date/period
Architectural style

Streetscape contribution

- ☐ Significant ☐ Contributory
☐ Borderline ☒ Non-contributory

Heritage listings

- ☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date
Source

Information source/s

Recommended conservation action

Suggested colour scheme(s)

NC RANGE



Historic Photo

Address 626 KING ST.

LGA ☒ South Sydney ☐ Marrickville

Owner MR & MRS. F. HRISTOFSKI.

Address 31 BATEMANS RD, GLADESVILLE,
2111.

Present name

Present use COMMERCIAL.

Former name

Former use

Date/period

Architectural style

Streetscape contribution

☐ Significant

☐ Contributory

☒ Borderline

☐ Non-contributory

Heritage listings

☐ Heritage Act

☐ Council LEP

☐ National Trust

☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

Suggested colour scheme(s)

NC RANGE



Historic Photo

Address 628-632 KING ST.
LGA ☒ South Sydney ☐ Marrickville

Owner MR. R. STUDDERT
Address 65 LOUISA RD, BIRCHGROVE,
2041.

Present name
Present use RETAIL / RESIDENTIAL

Former name WES'S BUILDINGS.
Former use

Date/period
Architectural style VICTORIAN FLIGREE.

Streetscape contribution

☐ Significant ☒ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

- REINSTATE METAL AWNINGS TO NOS 630 & 632 TO MATCH ORIGINAL
- REPLACE ALUMINIUM WINDOW WITH TRADITIONAL TIMBER FRAME.

Suggested colour scheme(s)

VIC: B, C, E or F



Historic Photo

Address 634 KING ST
LGA ☒ South Sydney ☐ Marrickville

Owner MR N MICHAELOPOULOS
Address 103 KING ST, NEWTOWN, 2042.

Present name AMP
Present use COMMERCIAL

Former name
Former use

Date/period
Architectural style

Streetscape contribution

☐ Significant ☐ Contributory
☐ Borderline ☒ Non-contributory

Heritage listings

☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date
Source

Information source/s

Recommended conservation action

Suggested colour scheme(s)

NC RANGE



Historic Photo

Address 636 KING ST.

LGA ☒ South Sydney ☐ Marrickville

Owner CAGEMA P/L

Address P.O. BOX 124, PADSTOW, 2211.

Present name

Present use RETAIL (VACANT).

Former name

Former use

Date/period

Architectural style

Streetscape contribution

- ☐ Significant ☒ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

- ☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

- REPLACE ALUMINIUM WINDOW WITH TRADITIONAL TIMBER FRAME.
- REPLACE MISSING URN FINIAL.

Suggested colour scheme(s)

VIC: B, C OR D



Historic Photo

Address 638 KING ST
LGA ☒ South Sydney ☐ Marrickville

Owner MR & MRS T.S. CLAYTON.
Address 638-638A KING ST, NEWTOWN, 2042.

Present name
Present use RETAIL / COMMERCIAL (VACANT).

Former name
Former use DENTAL LABORATORY.

Date/period
Architectural style

Streetscape contribution

- ☐ Significant ☐ Contributory
☒ Borderline ☐ Non-contributory

Heritage listings

- ☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Recommended conservation action

- RESTORE BUILDING TO ORIGINAL DETAIL.

Photo date

Source

Information source/s

Suggested colour scheme(s)

VIC: B, C OR D



Historic Photo

Address 640 KING ST.
LGA ☒ South Sydney ☐ Marrickville

Owner MRS. M. MASS
Address 45 CLYDE ST, NORTH BONDI, 2022.

Present name TAB
Present use TAB.

Former name
Former use

Date/period
Architectural style

Streetscape contribution

☐ Significant ☐ Contributory
☐ Borderline ☒ Non-contributory

Heritage listings

☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

Suggested colour scheme(s)

N/A



Historic Photo

Address 642 - 646 KING ST

LGA ☒ South Sydney ☐ Marrickville

Owner MR .S. CALLIL

Address 523 NEW CANTERBURY RD, DULWICH HILL, 2203.

Present name

Present use RESTAURANT /PERFORMING ARTS.

Former name

Former use

Date/period

Architectural style

Streetscape contribution

- ☐ Significant ☒ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

- ☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

- REPLACE ALUMINIUM WINDOWS WITH TRADITIONAL TIMBER FRAMES.

Suggested colour scheme(s)

EXISTING SCHEME
ACCEPTABLE.



Historic Photo

Address 654 KING ST
LGA ☒ South Sydney ☐ Marrickville

Owner
Address



Present name STARLAKE BODY REPAIRS
Present use CAR REPAIR.

Former name T. HODKINSON & CO. - TOD WILLIAMS ENG.
Former use IRONFOUNDERS - FOUNDERS.

Date/period c1900
Architectural style

Streetscape contribution

- ☐ Significant ☒ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

- ☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date c1912
Source J.S.M.N. p193.

Information source/s

Recommended conservation action

- RESTORE ALL WINDOW & DOOR OPENINGS.
- REINSTATE ORIGINAL PARAPET.

Suggested colour scheme(s)

FBK: A or D



Historic Photo

Address

LGA ☒ South Sydney ☐ Marrickville

Owner STARLAKE BODY REPAIRS P/L

Address 654 KING ST, NEWTOWN, 2042.

Present name STARLAKE BODY REPAIRS

Present use CAR REPAIR.

Former name

Former use

Date/period

Architectural style

Streetscape contribution

☐ Significant

☐ Contributory

☐ Borderline

☒ Non-contributory

Heritage listings

☐ Heritage Act

☐ Council LEP

☐ National Trust

☐ Local study

Recommended conservation action

Photo date

Source

Information source/s

Suggested colour scheme(s)

N/A



Historic Photo

Address

LGA ☒ South Sydney ☐ Marrickville

Owner STARLAKE BODY REPAIRS P/L
Address 654 KING ST, NEWTOWN, 2042.

Present name STARLAKE BODY REPAIR
Present use CAR REPAIR.

Former name
Former use

Date/period
Architectural style

Streetscape contribution

☐ Significant ☐ Contributory
☐ Borderline ☒ Non-contributory

Heritage listings

☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

Suggested colour scheme(s)

N/A



Historic Photo

Address 672 KING ST.
LGA ☒ South Sydney ☐ Marrickville

Owner LIANOS ENTERPRISES P/L
Address P.O. BOX 53, HAYMARKET, 2000.

Present name
Present use THEATRE (VACANT).

Former name
Former use THEATRE.

Date/period
Architectural style

Streetscape contribution

☒ Significant ☐ Contributory
☐ Borderline ☐ Non-contributory

Heritage listings

☐ Heritage Act ☐ Council LEP
☐ National Trust ☐ Local study

Photo date

Source

Information source/s

Recommended conservation action

• PREPARE CONSERVATION PLAN.

Suggested colour scheme(s)

INDIVIDUAL BUILDING

