
Attachment A8

Surveys





www.realserve.com.au 7729 929 20 .Aq SUTTONS GROUP OF 3D Laser Scanning Consulting Land Surveyors

COMMENTS

PLAN PREPARED FOR:

REF: 75183RL CHECKED: DW SHEET No. 1 OF 10 DRAWN : RL L.G.A.: LANE COVE CONTOUR INTERVAL: 0.25m SURVEY: RL LOCALITY: LONGUEVILLE OBIGIN OF LEVELS: SSM 49315 SCALE: NOT TO SCALE **GHA MUTAG** DATE: 15-05-2020

BEING No.118-130 EPSOM ROAD, ZETLAND, 2017 LOT 7 IN DP 24314 PLAN SHOWING GENERAL SITE CONDITIONS

THE SUBJECT LAND - LOT 7 DP 24134 IS AFFECTED BY COVENANT (VIDE DEALING No. F722199)

DENOTES TREE POSITION (NOT TO SCALE).

V3A 3TAO

TR7: TREE APPROX. 0.7Ø TRUNK 10 SPREAD & HEIGHT TR6 : TREE APPROX. 0.6Ø TRUNK 10 SPREAD & HEIGHT TR5 : TREE APPROX. 0.5Ø TRUNK 8 SPREAD & HEIGHT TR4: TREE APPROX. 0.4Ø TRUNK 8 SPREAD & HEIGHT TR3: TREE APPROX. 0.3Ø TRUNK 6 SPREAD & HEIGHT

Building Measurement Specialist

TREE LEGEND

BY SURVEY CALCULATION - 1.618 ha BY TITLE - DP 24134 - 1.618 ha AREA LOT 7 DP 24134:

(M) EASEMENT FOR DRAINAGE BURDENING PART OF THE SUBJECT LAND (VIDE DEALING No. F168968) (E) EASEMENT FOR DRAINAGE 3.05 WIDE BURDENING PART OF THE SUBJECT LAND (VIDE DEALING No. F722199) (C) EASEMENT FOR DRAINAGE BURDENING PART OF THE SUBJECT LAND (VIDE DEALING No. G167065) DAOA 278° 46' 50" 62·505 71:02 977 9 :N 185:687 786:281 GLASS & METAL BUILDING CORNER COORDINATES SHEEL 2 T LIBHS ZHEEL 3 SHEEL 9 SHEET 10 BBICK & METAL BUILDING No. 118-130 EPSOM ROAD DP 24134 EL9'7LZ 97Z 9 :N 658'SL9 788:3 CORNER COORDINATES SHEEL 5 ZHEEL J 6 LJJHS STRUCTURE METAL BUILDING DP 1220949 DP 830870

SHEEL 8


ALL DIMENSIONS ARE IN METRES.


- INDIRECT METHODS (WHERE VISIBLE) & ACCURATE TO APPROXIMATELY +/- 0.02m.
- THE LOCATION & LEVELS OF BUILDING ROOF FEATURES HAVE BEEN DETERMINED BY
 - ONLY THOSE SERVICES VISIBLE AT THE TIME OF SURVEY HAVE BEEN LOCATED.
 - OBTAINED FROM LAND REGISTRY SERVICES N.S.W. AND ARE SUBJECT TO FINAL


THE LOCATION OF EASEMENTS HAVE BEEN COMPILED FROM PLANS & RECORDS


- RESPONSIBLE FOR ANY ISSUES RESULTING FROM NON COMPLIANCE WITH THIS ADVICE. MARKS PRIOR TO COMMENCEMENT OF ANY WORKS. REALSERVE WILL NOT BE HELD WILL REQUIRE ADDITIONAL BOUNDARY SURVEY & PLACEMENT OF BOUNDARY/SETOUT
- ANY CONSTRUCTION OR WORKS RELYING ON CRITICAL SETBACKS FROM BOUNDARIES SERVICES & REPRESENT TITLE DIMENSIONS.
- MEASUREMENTS & REGISTERED PLANS OBTAINED FROM NSW LAND REGISTRY THE LOCATION OF PROPERTY BOUNDARIES HAVE BEEN COMPLIED FROM SURVEY
- 2SM 49315 RL 21.502 AHD (SOURCE: SCIMS 15-05-2020). LEVELS ARE BASED ON AUSTRALIAN HEIGHT DATUM (AHD). THE ORIGIN OF WHICH IS
- HARD COPY/DATA FILE.
- THESE GENERAL NOTES ARE ALWAYS SHOWN/KEPT ON ANY COPY OR EXTRACT OF THE THIS PLAN OR IN THE ASSOCIATED CAD FILE IS SUPPLIED ON THE CONDITION THAT
- NO NWOHS NOITES ARE AN INTEGRAL PART OF THIS PLAN. THE INFORMATION SHOWN ON


GENERAL /SPECIFIC NOTES

























Date: 20th May 2020

Our Ref: 75813

Instructed By: Suttons Group of Companies

Re: 118-130 Epsom Road, Zetland, NSW, 2017

Further to your instructions and for your private use we have surveyed, where accessible & for identification purposes only, the land comprised in Computer Folio Certificate Title Reference:

• 7/24134 being Lot 7 in Deposited Plan 24134

The Folio Certificate Search as obtained from NSW Land Registry Services is certified to 20/05/2020.

Location of Subject Land

Locality: Zetland

Local Government Area: Sydney

Parish: Alexandria County: Cumberland

The subject land is known as No. 118-130 Epsom Road has road frontages to Epsom Road and Link Road.

The area of the subject land is 1.618 ha (by Survey Calculation).

Improvements on the Subject Land

Erected on the subject land is a brick and metal industrial and office building attached to the building erected on the adjacent property, a metal building structure, a glass and metal building and a concrete, metal and glass building with carparking under. These building structures as surveyed generally stand within the subject property and the location relative to subject property boundaries is as shown on the accompanying plan. Encroachments are as noted below.

Fencing

The land is partially walled & fenced as shown on the accompanying plan.

Encroachments

In our opinion:

- The northern part of two shelter structures erected on the subject land stand and overhang over the adjoining land to the north (Lot 2 DP 830870) by up to 2.89 metres as shown.
- Part of the southern face of a concrete block wall erected on the adjoining land to the north (Lot 2 DP 830870) stands over the subject land by 0.07 metres as shown on the accompanying plan.
- The northern part of a bus shelter structure erected on Epsom Road to the south overhangs over the subject land by 0.43 metres as shown.

REALSERVE Pty Ltd ABN:61 442 770 200

02 9629 9377



Apart from fencing irregularities shown on the accompanying plan there appears to be no further visible encroachments by or upon the subject property as surveyed & where accessible.

Registered Encumbrances, Easements and Interests

Lot 7 DP 24134

- 1. Reservations and conditions in the Crown Grant(s).
- 2. Drainage Easement burdening the subject land (vide Dealing No. F168968) designated (M) as shown on the accompanying plan.
- 3. Easement for Drainage burdening the subject land (vide Dealing No. F722199) designated (E) as shown.
- 4. Covenant (vide Dealing No. F722199).
- 5. Easement for Drainage burdening the subject land (vide Dealing No. G167065) designated (C) as shown.

Boundary Reinstatement

The boundaries have been identified from title dimensions and survey measurements to marks & monuments recorded on existing registered survey plans of the subject and adjoining lands.

This report and accompanying plan have been prepared for Identification purposes only and as such is not a new survey of the title dimensions and should not be used for any other purpose other than to identify the subject land.

This survey & report is not registered at NSW Land Registry Services. Subsequent registered or other surveys in the area may affect boundary definition as shown in this report. Any differences so caused to the boundary definition in this report are beyond the control of the signing Registered Surveyor who can accept no responsibility for such differences.

This report is to be read in conjunction with the accompanying Plan of Identification Survey.

Delcep


David McCulloch (Registered Surveyor – Surveyor ID: 125)


Attachments


- Plan of Identification Survey


REALSERVE Pty Ltd ABN:61 442 770 200


www.realserve.com.au


































Date: 20th May 2020

Our Ref: 75812

Instructed By: Suttons Group of Companies

Re: 905 South Dowling Road, Zetland, NSW, 2017

Further to your instructions and for your private use we have surveyed, where accessible & for identification purposes only, the land comprised in Computer Folio Certificate Title Reference:

• 2/830870 being Lot 2 in Deposited Plan 830870

The Folio Certificate Search as obtained from NSW Land Registry Services is certified to 20/05/2020.

Location of Subject Land

Locality: Zetland

Local Government Area: Sydney

Parish: Alexandria County: Cumberland

The subject land is known as No. 905 South Dowling Road has road frontages to South Dowling Road and Link Road.

The area of the subject land is 2.467 ha (by Survey Calculation).

Improvements on the Subject Land

Erected on the subject land is a brick, concrete and metal industrial building, two concrete and glass buildings, a brick building and a brick building attached to the building erected on the adjacent property to the south. These building structures as surveyed generally stand within the subject property and the location relative to subject property boundaries is as shown on the accompanying plan. Encroachments are as noted below.

Fencing

The land is partially walled and fenced as shown on the accompanying plan.

Encroachments

In our opinion:

- Part of the southern face of a concrete block wall erected on the subject land stands over the adjoining land to the south by 0.07 metres as shown on the accompanying plan.
- The northern part of two shelter structures erected on the adjoining land to the south (Lot 7 DP 24134) stand and overhang over the subject land by up to 2.89 metres as shown.

REALSERVE Pty Ltd ABN:61 442 770 200



Apart from fencing irregularities shown on the accompanying plan there appears to be no further visible encroachments by or upon the subject property as surveyed & where accessible.

Registered Encumbrances, Easements and Interests

Lot 2 DP 830870

- 1. Reservations and conditions in the Crown Grant(s).
- 2. Covenant (vide Dealing No. F723355) designated (G) as shown on the accompanying plan.
- 3. Covenant (vide Dealing No. F979611) designated (H) as shown.
- 4. Covenant (vide Dealing No. G206463) designated (Z) as shown.
- 5. Covenant (vide Dealing No. K920060) designated (F) as shown.
- 6. Easement for Drainage 3.05 metres wide benefiting part of the subject land (vide Dealing No. F722199 & F723355) designated (D) as shown.
- 7. Easement for Drainage 3.05 metres wide burdening part of the subject land (vide Dealing No. F722677 & F723355) designated (A) as shown and, Right of Carriageway 1.875 metres wide and variable width (vide DP 830870) designated (Y) as shown.
- 8. Easement to Drain Water 3 metres wide benefiting the subject land (vide DP 830870).

Boundary Reinstatement

The boundaries have been identified from title dimensions and survey measurements to marks & monuments recorded on existing registered survey plans of the subject and adjoining lands.

This report and accompanying plan have been prepared for Identification purposes only and as such is not a new survey of the title dimensions and should not be used for any other purpose other than to identify the subject land.

This survey & report is not registered at NSW Land Registry Services. Subsequent registered or other surveys in the area may affect boundary definition as shown in this report. Any differences so caused to the boundary definition in this report are beyond the control of the signing Registered Surveyor who can accept no responsibility for such differences.

This report is to be read in conjunction with the accompanying Plan of Identification Survey.

Occep

David McCulloch (Registered Surveyor – Surveyor ID: 125)

<u>Attachments</u>

Plan of Identification Survey

REALSERVE Pty Ltd ABN:61 442 770 200

Suite 29, 6 Meridian Place

